





Texpri 19-25 Anti-Bleeding WB

Code 996296

PRODUCT DESCRIPTION

Water based ink for textile printing. Underbase grey for polyester fabrics.

APPLICATION FIELDS

Direct textile printing. For ready-to-wear or pre-cut articles.

APPLICATION PROCESS

| Substrates | PolyesterBlended polyesterThe substrates may be coloured |
|----------------------|--|
| Th/cm | • Max 43 Th/cm (110 Th/inch) |
| Emulsion | Zero-In Astra Zero-In Universal Plus |
| Squeegee | Square edge • Squeegee hardness 60 - 65 Shores |
| Curing | • 120/140°C for 2-3 minutes |
| Auxiliaries | See TDS "Auxiliaries for water based inks" |
| Cleaning | Screenclean ST |
| Storage | Away from direct sunlightAt a temperature between 15-35°C |
| Package | • 5 kg |
| Safety Data Sheet | Available upon request |

GENERAL FEATURES

- High opacity on polyester and blended fabrics
- · Quick intermediate drying (flash cure)
- · Good printability
- Overprintable with Aqua



PREPARATION

Ready-to-use ink.
Homogenize well before using it.
The possible addition of water allows to reduce ink viscosity.

APPLICATION

For the best colour opacity and brightness, during printing, it is recommended to adjust the out of contact and the pressure of the squeegee at their best, in order to obtain an ink film that can remain onto the surface of the substrate.

The opacity is influenced by the kind of drawing, the th/cm screen number, the squeegee, the pressure and the printing speed.

The ink is used like underbase to reduce the substrate influence on polyester fabrics. It is possible to overprint, after intermediate drying, with *Aqua*.

CURING

Curing must take place at 120/140°C during 3/2 minutes.









SPECIAL INSTRUCTIONS

- Always test the print characteristics, before starting production.
- Always test the bleeding fastness of the substrates, before starting production.
- M996296 Texpri 19-25 Anti-Bleeding WB does not contain any hazardous substances and it is suitable for direct skin contact.
- Before using it, make sure that squeegees, countersqueegees, screens and cases have been cleaned well from possible rests of other inks series. So, possible "pollution", deriving from other ink series, can be avoided.
- Before use, make sure that the squeegees, scrapers, pictures and containers are well cleaned of any residues from other ink series. In this way, possible "contaminations" deriving from the other series of inks are avoided.

EQUIPMENT

Indicated for using onto automatic, semi-automatic and manual machines.

IMPORTANT NOTE

The information given in this technical sheet is not intended to be exhaustive and any person, using the product for any purpose other than that specifically recommended in this sheet without first obtaining written confirmation from us to the suitability of the product for the intended purpose, does so at his own risk.

While we endeavour to ensure that all advice we give about the product is correct, we have no control over either the quality or condition of the substrate or the many factors affecting the use and application of the product.

Therefore, unless we specifically agree in writing to do so, we do not accept any liability whatsoever or howsoever arising for the performance of the product or for any loss or damage arising out of the use of the product.

The information contained in this sheet is liable to modification from time to time in the light of experience and our policy of continuous product development.

WARNING

This technical data sheet does not replace either the Safety Data Sheet or the specific Conformity Declaration. These documents may be required to our SHEQ (Product safety office), at the following e-mail address: safety@eptainks.com

The technical data sheet does not relieve the printer, who remains the only responsible of the respect of the regulations, the specifications and the related required certifications of the finished items.

